

# **IEC 61508 Functional Safety Assessment**

Project: Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter

> Customer: Magnetrol International, Inc. Aurora, IL USA

Contract No.: Q09/10-39, Q14/09-006 Report No.: MAG 09/10-39-R005 Version V1, Revision R4, December 5, 2014 Griff Francis

The document was prepared using best effort. The authors make no warranty of any kind and shall not be liable in any event for incidental or consequential damages in connection with the application of the document. © All rights reserved.



## Management Summary

This report summarizes the results of the functional safety assessment according to IEC 61508 carried out on the:

Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter

The functional safety assessment performed by *exida* consisted of the following activities:

- *exida* assessed the systematic capability through an analysis of proven-in-use data and creation of a detailed safety case against the requirements of IEC 61508.
- *exida* reviewed and assessed a detailed Failure Modes, Effects, and Diagnostic Analysis (FMEDA) of the devices to document the hardware architecture and failure behavior.

The functional safety assessment was performed to the requirements of IEC 61508, SIL 3. All documents referenced in sections 2.4.1 and 2.4.3 were reviewed and form the basis of this assessment.

The results of the Functional Safety Assessment can be summarized by the following statements:

The Eclipse Enhanced Model 705 3X Level Transmitter was found to meet the requirements of SIL 2 for random integrity @HFT=0, SIL 3 for random integrity @ HFT=1 and SIL 3 for systematic capability.

The manufacturer will be entitled to use the Functional Safety Logo.





# **Table of Contents**

| Ma | nage  | ement Summary  | 2  |
|----|-------|--|----|
| 1  | Pur   | pose and Scope   | 4  |
|    | 1.1   | Tools and Methods used for the assessment  | 4  |
| 2  | Proj  | ect management   | 5  |
|    | 2.1   | exida  | 5  |
|    | 2.2   | Roles of the parties involved  | 5  |
|    | 2.3   | Standards / Literature used  | 5  |
|    | 2.4   | Reference documents  | 5  |
|    |       | 2.4.1 Documentation provided by Magnetrol International, Inc.                                      | 5  |
|    |       | 2.4.2 Documentation provided by Magnetrol International, Inc. for Re-Certification<br>October 2014 | 7  |
|    |       | 2.4.3 Documentation generated by <i>exida</i>  | 8  |
| 3  | Pro   | duct Description   | 10 |
|    | 3.1   | Scope of Analysis  | 11 |
| 4  | IEC   | 61508 Functional Safety Assessment   | 11 |
|    | 4.1   | Methodology  | 11 |
|    | 4.2   | Assessment level   | 12 |
| 5  | Res   | ults of the IEC 61508 Functional Safety Assessment   | 13 |
|    |       | 5.1.1 Validation   | 13 |
|    |       | 5.1.2 Modifications  | 13 |
|    |       | 5.1.3 User documentation   | 13 |
|    |       | 5.1.4 Update for Certification Renewal   | 13 |
|    | 5.2   | Hardware Assessment  | 15 |
| Те | rms a | and Definitions  | 17 |
| 6  | Stat  | us of the document   | 18 |
|    | 6.1   | Liability  | 18 |
|    | 6.2   | Releases   | 18 |
|    | 6.3   | Future Enhancements  | 18 |
|    | 6.4   | Release Signatures   | 19 |

# 1 Purpose and Scope

This document shall describe the results of the IEC 61508 functional safety assessment of the Magnetrol International, Inc.:

> Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter

by *exida* according to the requirements of IEC 61508: ed1, 2000.

The purpose of the assessment was to investigate the compliance of:

- the Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter with the technical IEC 61508-2 and -3 requirements for SIL 3 and the derived product safety property requirements

and

- the Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter development processes, procedures and techniques as implemented for the safety-related deliveries with the managerial IEC 61508-1, -2 and -3 requirements for SIL 3.

and

- the Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter hardware analysis represented by the Failure Mode, Effects and Diagnostic Analysis with the relevant requirements of IEC 61508-2.

The assessment has been carried out based on the quality procedures and scope definitions of *exida*.

The results of this assessment provide the safety instrumentation engineer with the required failure data as per IEC 61508 / IEC 61511 and confidence that sufficient attention has been given to systematic failures during the development process of the device.

#### 1.1 Tools and Methods used for the assessment

This assessment was carried by using the *exida* Safety Case tool. The Safety Case tool contains the *exida* scheme which includes all the relevant requirements of IEC 61508.

For the fulfillment of the objectives, expectations are defined which builds the acceptance level for the assessment. The expectations are reviewed to verify that each single requirement is covered. Because of this methodology, comparable assessments in multiple projects with different assessors are achieved. The arguments for the positive judgment of the assessor are documented within this tool and summarized within this report.

# 2 Project management

## 2.1 *exida*

*exida* is one of the world's leading accredited Certification Bodies and knowledge companies specializing in automation system safety and availability with over 300 years of cumulative experience in functional safety. Founded by several of the world's top reliability and safety experts from assessment organizations and manufacturers, *exida* is a global company with offices around the world. *exida* offers training, coaching, project oriented system consulting services, safety lifecycle engineering tools, detailed product assurance, cyber-security and functional safety certification, and a collection of on-line safety and reliability resources. *exida* maintains a comprehensive failure rate and failure mode database on process equipment based on 100 billion hours of field failure data.

#### 2.2 Roles of the parties involved

| Magnetrol International, Inc. | Manufacturer of the Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter   |  |  |  |  |
|-------------------------------|--|--|--|--|--|
| exida                         | Performed the hardware assessment  |  |  |  |  |
| exida                         | Performed the Functional Safety Assessment per the accredited <i>exida</i> scheme. |  |  |  |  |

Magnetrol International, Inc. contracted *exida* in October 2009 with the IEC 61508 Functional Safety Assessment of the above mentioned devices. Magnetrol International, Inc. contracted *exida* again in September 2014 to renew the certification.

## 2.3 Standards / Literature used

The services delivered by *exida* were performed based on the following standards / literature.

| [N1] | IEC 61508 (Parts 1 - 7): | Functional Safety of Electrical/Electronic/Programmable |  |  |  |
|------|--------------------------|---|--|--|--|
|      | 2000                     | Electronic Safety-Related Systems                       |  |  |  |

#### 2.4 Reference documents

#### 2.4.1 Documentation provided by Magnetrol International, Inc.

|      | [Safety Case Doc]; Rev;<br>Date | Description   |
|------|---------------------------------|---|
| [D1] | [D01]; V0R1; 6/3/2010           | Functional Safety Management Plan - Not required for PIU with modification restrictions, included for reference |
| [D2] | [D110]; 10/28/2005              | EMC CE COMPLIANCE TEST REPORT Enhanced<br>Model 705 Eclipse Transmitter   |
| [D3] | [D111]; 11/1/2003               | WIB Evaluation of Eclipse 705   |
| [D4] | [D119]; 3/29/2011               | exida Validation Test Execution Phase Checklist   |

| [D5]  | [D150];                           | <i>exida</i> Functional Safety Assessment Phase Verification Checklist                                       |  |  |
|-------|-----------------------------------|--|--|--|
| [D6]  | [D160]; 6/1/2010                  | Product Safety Manual  |  |  |
| [D7]  | [D161]; NA; 7/20/2010             | exida Safety Manual Checklist  |  |  |
| [D8]  | [D162]; 9/1/2007                  | Eclipse 3X Installation and Operating Manual   |  |  |
| [D9]  | [D165]; V3R1; 2/11/2010           | Failure Modes, Effects and Diagnostics Analysis (FMEDA) Report   |  |  |
| [D10] | [D166];                           | exida FMEDA Document Checklist   |  |  |
| [D11] | [D181]; Rev 12; 7/12/2011         | Engineering Change Request And Change Notice   |  |  |
| [D12] | [D189]; 3/29/2011                 | exida Modification Phase Verification Checklist  |  |  |
| [D13] | [D20]; 5/31/2011                  | ISO 9001 Certificate   |  |  |
| [D14] | [D21]; Rev 1.3; 12/4/2009         | Magnetrol SAFETY CRITICAL PRODUCT<br>DEVELOPMENT AND MAINTENANCE   |  |  |
| [D15] | [D22]; Rev 23; 8/3/2009           | Quality Management System Manual   |  |  |
| [D16] | [D23]; Rev 1.1; 7/1/2009          | C Coding Standard for Safety Related Software<br>Development   |  |  |
| [D17] | [D24]; Rev 14; 7/21/2010          | Supply Base Control Plan (Vendor Qualification Procedure)  |  |  |
| [D18] | [D25]; 7/27/2009                  | Magnetrol Software Development Methodology   |  |  |
| [D19] | [D26];                            | Safety Training Records  |  |  |
| [D20] | [D27]; Rev 1; 12/16/2010          | RMA Processing   |  |  |
| [D21] | [D28]; Rev 4; 7/29/2010           | Corrective Action Procedure  |  |  |
| [D22] | [D29]; Rev 0; 7/14/2011           | Customer Notification  |  |  |
| [D23] | [D30]; V0 R2; 7/12/2011           | Safety Requirements Specification - Not required for PIU with modification restrictions; added for reference |  |  |
| [D24] | [D31];                            | exida SRS Document Checklist   |  |  |
| [D25] | [D32]; 7/13/2011                  | Safety Requirements Specification Review Meeting<br>Minutes  |  |  |
| [D26] | [D45]; 6/2/2005                   | Enhanced Model 705 Warnings and Faults for SIL 1 and SIL 2   |  |  |
| [D27] | [D46]; V1R1; 4/29/2011            | Proven Operational Experience Calculation and Report   |  |  |
| [D28] | [D47]; 4/29/2011                  | Eclipse 3X Proven In Use Data  |  |  |
| [D29] | [D48]; 3/29/2011                  | exida Proven In Use Checklist  |  |  |
| [D30] | [D53]; 4/5/2010                   | Fault Injection Test Plan  |  |  |
| [D31] | [D54];                            | exida HW Fault Injection Test Verification Checklist   |  |  |
| [D32] | [D55]; see individual schematics; | Eclipse 3x Schematics  |  |  |

| [D33] | [D56];  | Eclipse 3x schematics with fault injection points |
|-------|---|---|
| [D34] | 34][D57]; Rev4; 7/15/2011Fault Injection Test Results |   |
| [D35] | [D68]; 7/26/2011 Component Level FMEDA                |   |
| [D36] | [D71];  | Detailed Software Design Specifications           |
| [D37] | [D80]; 1.0; 6/9/2010                                  | IEC 61508 Tables not covered in FSM Plan          |

## 2.4.2 Documentation provided by Magnetrol International, Inc. for Re-Certification October 2014

|       | Document Number,<br>Revision |   |  |  |
|-------|------------------------------|---|--|--|
|       | Date                         | File Name   | Description                                      |  |
| [D38] | _,_,27 Aug 2013              | New Product<br>Development Process<br>Flow.pdf      | Overall Development Process                      |  |
| [D39] |                              | Dev Process Steps.xlsx                              | Overall Development Process- Step<br>Description |  |
| [D40] | SLA-007, 00, 8 Jul<br>2013   | SLA007.pdf  | Modification Procedure                           |  |
| [D41] | SKA-002, 14, 23 Sep<br>2013  | SKA002.pdf  | Modification Procedure - EC                      |  |
| [D42] | _,_,25 Sep 2014              | 705-51A<br>SHIPMENTS.xlsx                           | Shipment Records                                 |  |
| [D43] | _,_,18 Sep 2014              | 705 3X SIL RMAs<br>SUMMARY 080111 TO<br>091614.xlsx | Field Returns Records                            |  |
| [D44] | CERT-0079004, 28 Apr<br>2014 | ISO 9001-2008<br>Certificate - May<br>2014.pdf      | ISO 900x Certificate                             |  |
| [D45] | 094-6052, G, 18 Jun<br>2010  | 094-5062-A.PDF                                      | SCHEMATIC, ENHANCED 705<br>DIGITAL P.C. BOARD    |  |
| [D46] | 094-5062, A, 8 Jan<br>2008   | 094-6052-G.PDF                                      | SCHEMATIC, HART<br>WIRING BOARD                  |  |
| [D47] | 094-6051, N, Oct 2009        | 094-6051-N.PDF                                      | SCHEMATIC,<br>ENHANCED 705<br>ANALOG P.C. BOARD  |  |
| [D48] | _,_,3 Oct 2014               | 705 3X SIL 2<br>CHANGES<br>100314.xlsx              | Hardware Change List                             |  |
| [D49] | _,_, 20 Jun 2011             | SC-1260.1AMDL 705<br>3X HART 5 TO 6                 | Validation Test Results                          |  |

|       |                             | TESTING.xlsx  |                                  |
|-------|-----------------------------|---|----------------------------------|
| [D50] | _,_, 1 Apr 2011             | M705 3x HART 5 to 6<br>Upgrade Common<br>Practice Commands<br>Tests.pdf               | Validation Test Results 2        |
| [D51] | _,_, 1 Apr 2011             | M705 3x HART 5 to 6<br>Upgrade Data Link<br>Layer Tests.pdf                           | Validation Test Results 3        |
| [D52] | _,_, 1 Apr 2011             | M705 3x HART 5 to 6<br>Upgrade Universal<br>Commands Tests.pdf                        | Validation Test Results 4        |
| [D53] | _,_, 18 Nov 2014            | Exida summary of Rev<br>N schematic changes<br>for Fid Ticks over<br>temperature.xlsx | Validation Test Results 5        |
| [D54] | 57-651.3,_, Mar 2012        | 57-651.3 Eclipse 705<br>SIL IO.pdf  | Safety Manual                    |
| [D55] | 3177-00755,_, 6 Jan<br>2010 | ECN 3177-755 screen shot.docx   | Engineering Change Documentation |
| [D56] | _,_,28 Mar 2011             | M705 3X HART 5 TO 6<br>MIGRATION IMPACT<br>ANALYSIS.docx                              | Impact Analysis Record           |

# 2.4.3 Documentation generated by exida

| [R1] | MAG 09-10-39 R005<br>V1R4 IEC 61508<br>Assessment Eclipse<br>3X.doc, 5 December 2014 | IEC 61508 Functional Safety Assessment, Eclipse<br>Enhanced Model 705 3X Guided Radar Level Transmitter<br>(this report) |
|------|--|--|
| [R2] | MAG 09/10-39 R001<br>V3R1 FMEDA Report , 26<br>July 2011                             | Eclipse Enhanced Model 705 3X Guided Radar Level<br>Transmitter FMEDA Report   |
| [R3] | MAG 09/10-39 R004<br>V1R1 PIU Report , 29 Apr<br>2011                                | Eclipse Enhanced Model 705 3X Guided Radar Level<br>Transmitter PIU Analysis-Report                                      |
| [R4] | Eclipse 3X IEC61508<br>SafetyCase<br>1Aug2011.esc                                    | Safety Case DB- previous PIU certification   |
| [R5] | Magnetrol 705 PIU<br>Spreadsheet.xls, 29 Oct<br>2014                                 | Calculation of actual field failure rate / PIU Analysis  |

| [R6] | MAG 705 V1R1 Change<br>Audit Checklist_form.xls,<br>19 Nov 2014           | Change Audit Checklist (referenced by SafetyCaseWB) |
|------|---|---|
| [R7] | MAG 705 V1R1 Safety<br>Case WB-61508<br>v1.7.2d.xlsm, V1R2, 5<br>Dec 2014 | SafetyCaseWB  |

# **3 Product Description**

The Eclipse Enhanced Model 705 Guided Wave Radar Level Transmitter is a loop-powered, 24 VDC level transmitter, based on Guided Wave Radar (GWR) technology. For safety instrumented systems usage it is assumed that the 4 - 20mA output is used as the primary safety variable. The analog output meets NAMUR NE 43 (3.8mA to 20.5mA usable). The transmitter contains self-diagnostics and is programmed to send its output to a specified failure state, either low or high upon internal detection of a failure (output state is programmable). The device can be equipped with or without display.



Table 1 lists the versions of the Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter that have been considered for the hardware assessment.

#### Table 1 Version overview



Guided Wave Radar is based upon the principle of TDR (Time Domain Reflectometry). TDR utilizes pulses of electromagnetic energy transmitted down a probe. When a pulse reaches a surface that has a higher dielectric than the air/vapor in which it is traveling, the pulse is reflected. An ultra high-speed timing circuit precisely measures the transit time and provides an accurate level measurement.

Choosing the proper Guided Wave Radar (GWR) probe is the most important decision in the application process. The probe configuration establishes fundamental performance characteristics. Coaxial, twin element (rod or cable), and single element (rod or cable) are the three basic configurations. The probe for use with the Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter should be selected as appropriate for the application. Careful selection of probe design and materials for a specific application will minimize media build-up on the probe.

The Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter is classified as a Type B<sup>1</sup> device according to IEC61508, having a hardware fault tolerance of 0.

#### 3.1 Scope of Analysis

The following were considered in this analysis:

| Digital Board | 094-6052, Rev F |
|---------------|-----------------|
| Analog Board  | 094-6051 Rev M  |
| Wiring Board  | 094-5062, Rev A |

The IEC61508 certified 705-51A\*-\*\*\* will be distinguished from the previous non-certified version by the serial number. The certification will apply to serial numbers starting at 648100-01-001.

## 4 IEC 61508 Functional Safety Assessment

The IEC 61508 Functional Safety Assessment was performed based on the information received from Magnetrol International, Inc. and is documented in this section.

#### 4.1 Methodology

As part of the IEC 61508 functional safety assessment, the following aspects have been reviewed: Documents:

- FMEDA
- safety manual
- instruction manual
- HW fault inject test plan and results verification
- SW design specification
- EMC test report
- Validation test results
- Corrective Action and prevention action plan/process

No ASICs are used in this product

No safety related communications are used in this product

Proven-In-Use (PIU) assessment provides for the prevention of systematic failures for pre-existing devices with a proven history of successful operation. As part of the IEC 61508 PIU assessment, the following aspects have been reviewed:

• PIU data and Operational excellence calculation/report (Evidence that the equipment is proven-in-use; Analysis of field failure rates to ensure that no systematic faults exist in the product)

<sup>&</sup>lt;sup>1</sup> Type B component: "Complex" component (using micro controllers or programmable logic); for details see 7.4.3.1.3 of IEC 61508-2.

- A number of functional safety lifecycle assessment aspects are not required due to PIU assessment:
  - o SRS
  - o FSM Plan
  - o Configuration management
  - o Validation of development tools
  - Validation test plan
  - o Architecture design
  - Integration and Unit test plans
  - Development process

## 4.2 Assessment level

The Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter has been assessed per IEC 61508 to the following levels:

- SIL 2 random integrity for single device (Hardware Fault Tolerance = 0)
- SIL 3 random integrity for multiple devices (Hardware Fault Tolerance = 1)

The development procedures were assessed according to PIU criteria as suitable for use in applications with a maximum Safety Integrity Level of 3 (SIL 3 capability) according to IEC 61508.

# 5 Results of the IEC 61508 Functional Safety Assessment

*exida* assessed a detailed Failure Modes, Effects, and Diagnostic Analysis (FMEDA) [R2] of the Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter to document the hardware architecture and failure behavior. The Safety Case created for the Eclipse Enhanced Model 705 3X documents this assessment.

*exida* assessed failure history of the Eclipse Enhanced Model 705 3X Guided Radar Level Transmitter see [D28] and performed a detailed analysis of the data provided, see [D27]. This PIU assessment is done in place of a detailed functional safety assessment for systematic failures. The Safety Case created for the Eclipse Enhanced Model 705 3X documents this assessment.

The requirements of SIL 3 have been met in this area.

## 5.1.1 Validation

Validation Testing results were reviewed via a set of documented tests (see [D2] and [D3]). As the Eclipse Enhanced Model 705 3X consists of simple electrical devices with a straightforward safety function, there is no separate integration testing necessary.

Procedures are in place for corrective actions to be taken when tests fail as documented in [D25].

Items from IEC **61508-2, Table B.3** include functional testing, project management, documentation, and black-box testing (for the considered devices this is similar to functional testing). Field experience and proven-in-use data are included for systematic capability. This meets SIL 3.

Items from IEC **61508-2**, **Table B.5** include functional testing and functional testing under environmental conditions, Interference surge immunity testing, fault insertion testing, project management, documentation, static analysis, dynamic analysis, and failure analysis, expanded functional testing and black-box testing. This meets SIL 3.

## 5.1.2 Modifications

Modifications are done per the Magnetrol International, Inc. Modification Procedures [D40] and [D41]. Impact Analyses are performed on changes to safety certified products. This meets SIL 3.

## 5.1.3 User documentation

Magnetrol International, Inc. created a Safety Manual for the Eclipse Enhanced Model 705 3X, see [D6]. This safety manual was assessed by *exida*. The final version is considered to be in compliance with the requirements of IEC 61508. The document includes all required reliability data and operations, maintenance, and proof test procedures.

# The analysis shows that the Eclipse Enhanced Model 705 3X meets the systematic capability requirements of IEC 61508 SIL 3.

## 5.1.4 Update for Certification Renewal

Product changes made since the last certification [D48] were reviewed. A representative Impact Analysis [D57] and associated Validation Tests [D49] through [D53] were also reviewed.

The current revision of the schematics [D45], [D46] and [D47] were reviewed. The FMEDA did not need to change.

The Shipment [D42] and Field Return [D43] Records were reviewed and an actual field failure rate calculated. This was compared with the FMEDA calculations [R5] and found consistent.

The current revision of the Safety Manual [D54] was reviewed.

## 5.2 Hardware Assessment

To evaluate the hardware design of the Eclipse Enhanced Model 705 3X, a Failure Modes, Effects, and Diagnostic Analysis was performed by *exida*. This is documented in [R2]. The FMEDA was verified using Fault Injection Testing, see [D34].

A Failure Modes and Effects Analysis (FMEA) is a systematic way to identify and evaluate the effects of different component failure modes, to determine what could eliminate or reduce the chance of failure, and to document the system in consideration. An FMEDA (Failure Mode Effect and Diagnostic Analysis) is an FMEA extension. It combines standard FMEA techniques with extension to identify online diagnostics techniques and the failure modes relevant to safety instrumented system design.

From the FMEDA, failure rates are derived for each important failure category. Table 2 lists these failure rates separately for each output type as reported in the FMEDA reports. The failure rates are valid for the useful life of the devices. Table 3 lists sample  $PFD_{AVG}$  results.

| Device   | $\lambda_{sd}$ | $\lambda_{su}^2$ | $\lambda_{dd}$ | $\lambda_{du}$ | SFF   |
|--|----------------|------------------|----------------|----------------|-------|
| Eclipse Enhanced Model 705, 705-51A*-***,<br>Low Trip  | 0 FIT          | 600 FIT          | 847 FIT        | 154 FIT        | 90.4% |
| Eclipse Enhanced Model 705, 705-51A*-***,<br>High Trip | 0 FIT          | 624 FIT          | 847 FIT        | 130 FIT        | 91.9% |

#### Table 2 Failure rates according to IEC 61508

#### Table 3 Sample PFD<sub>AVG</sub> Results

| Device                                      | Proof Test<br>Coverage | PFD <sub>AVG</sub> | % of SIL 2<br>Range |
|---|------------------------|--------------------|---------------------|
| Eclipse Enhanced Model 705 3X, 705-51A*-*** | 94%                    | 1.06E-03           | 10.6%               |

For low demand SIL 2 applications, the PFD<sub>AVG</sub> value of the Safety Instrumented Function needs to  $be \ge 10^{-3}$  and  $< 10^{-2}$ . The FMEDA report [R2] lists the percentage of this budget that the Eclipse Enhanced Model 705 3X uses. Considering a proof test is performed every year, the Eclipse Enhanced Model 705 3X model uses 10.6% of the PFD<sub>AVG</sub> budget.

These results must be considered in combination with  $PFD_{AVG}$  of other devices of a Safety Instrumented Function (SIF) in order to determine suitability for a specific Safety Integrity Level (SIL). The Safety Manual states that the application engineer should calculate the  $PFD_{AVG}$  for each defined safety instrumented function (SIF) to verify the design of that SIF.

<sup>&</sup>lt;sup>2</sup> It is important to realize that the "no effect" failures are included in the "safe undetected" failure category according to IEC 61508. Note that these failures on their own will not affect system reliability or safety, and should not be included in spurious trip calculations

The architectural constraints requirements of IEC 61508-2, Table 2, are also reviewed. The Safe Failure Fractions (SFF) for both Eclipse Enhanced Model 705 3X configurations are greater than 90%. Therefore the Eclipse Enhanced Model 705 3X can be used in SIL 2 applications, in simplex (single device, HFT = 0) mode and SIL 3 applications in redundant (multiple devices, HFT = 1) mode.

The analysis shows that the design of the Eclipse Enhanced Model 705 3X meets the hardware requirements of IEC 61508 SIL 2, single device (HFT = 0) and SIL 3, multiple devices (HFT = 1).

# **Terms and Definitions**

| Fault tolerance    | Ability of a functional unit to continue to perform a required function in the presence of faults or errors (IEC 61508-4, 3.6.3)  |
|--------------------|---|
| FIT                | Failure In Time (1x10 <sup>-9</sup> failures per hour)  |
| FMEDA              | Failure Mode Effect and Diagnostic Analysis   |
| HFT                | Hardware Fault Tolerance  |
| Low demand mode    | Mode, where the frequency of demands for operation made on a safety-<br>related system is no greater than one per year and no greater than twice the<br>proof test frequency.                         |
| PFD <sub>AVG</sub> | Average Probability of Failure on Demand  |
| PIU                | Proven-In-Use   |
| SFF                | Safe Failure Fraction summarizes the fraction of failures, which lead to a safe state and the fraction of failures which will be detected by diagnostic measures and lead to a defined safety action. |
| SIF                | Safety Instrumented Function  |
| SIL                | Safety Integrity Level  |
| SIS                | Safety Instrumented System – Implementation of one or more Safety Instrumented Functions. A SIS is composed of any combination of sensor(s), logic solver(s), and final element(s).                   |
| HART               | Highway Addressable Remote Transducer   |
| Type B (sub)system | "Complex" (sub)system (using micro controllers or programmable logic); for details see 7.4.4.1.3 of IEC 61508-2   |

## 6 Status of the document

#### 6.1 Liability

*exida* prepares reports based on methods advocated in International standards. Failure rates are obtained from a collection of industrial databases. *exida* accepts no liability whatsoever for the use of these numbers or for the correctness of the standards on which the general calculation methods are based.

#### 6.2 Releases

| Version:         | V1            |   |  |
|------------------|---------------|---|--|
| Revision:        | R4            |   |  |
| Version History: | V0, R1:       | Internal Draft; 15 July, 2011   |  |
|                  | V1, R1:       | ready to release, but changed SIL after final review                              |  |
|                  | V1, R2:       | changed p4 and p11 to clarify the restriction on the safety critical portion only |  |
|                  | V1, R3:       | released, 5 Aug 2011  |  |
|                  | V1, R4:       | updated for re-certification, Q14/09-060; Griff Francis, 5 Dec 2014               |  |
| Author:          | Griff Francis |   |  |
| Review:          | V0, R1:       | Rudolf Chalupa  |  |
|                  | V1, R1:       | Rudolf Chalupa  |  |
|                  | V1, R4:       | Rudolf Chalupa  |  |
|                  | <u> </u>      |   |  |

Release status: Released to Customer

#### 6.3 Future Enhancements

At request of client.

## 6.4 Release Signatures

Briff Granis

Griff Francis, Senior Safety Engineer

The Cyzallinas

John Yozallinas, Senior Safety Engineer

Rudolf P. Chalupa

Rudolf Chalupa, Senior Safety Engineer